Date:

Thursday, 5/25/2006 11:33:14 AM

Linda Lacelle

Process Sheet

Customer Job Number : CU-DAR001 Dart Helicopters Services

: 27217

Estimate Number

: 10599

P.O. Number

:NA

This Issue

Prsht Rev.

First Issue

: 5/25/2006

: NC

: NIA

S.O. No. : 1/ /A

: PURCHASED PARTS

: 27217 Previous Run

Written By

Checked & Approved By

Comment

: Est.

B 01.06.08

Now laser cut EC

Drawing Name

: D2506

Part Number Drawing Number

: D2506 REV D1

: LABEL PLATE

Project Number Drawing Revision

: N/A : D1

Material **Due Date**

:NIA : 6/1/2006

Qty:

Um:

Each

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

304/316 .040 Sheet

1.0

M304S20GA

1.2810 sf(s)/Unit

Total: 32.0250 sf(s)

304/316 .040 Sheet

Batch: M19093

11101261

2.0

Comment: Qty.:



Comment: FLOW WATER JET

1-Cut as per Dwg D

Dwg Rev: 01 Prog Rev: 01



2-Deburr if necessary

3.0

INSPECT PARTS AS THEY COME OFF MACHINE



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

4.0 QC8

Comment: SECOND

SMALL FAB 1



5.0

SMALL & MEDIUM FAB RESOURCE 1





1-Deburr if necessary.

06:06:14



W/O:		WORK ORDER CHANGES						
DATE	STEP	PROCEDURE CHANGE		Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector
	•							
			11					
i								

NCR:		WORK ORDER NON-CONFORMANCE (NCR)										
		Description of NC		Corrective Action Section B		Verification	Annroyal	Approval				
DATE	STEP	Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date	Section C	Approval Design Mgr	. Approval QC Inspector				
						+	:					
				i i	2			-				
								÷				
٠				10			1					
		£)						inter				

Part No:	PAR #:	Fault Category: NCR:	Yes (No) DQA:	Date: <u>0(40764</u> ^
NOTE: Date & initial all entries			QA: N/C Closed:	Date:

Date: Thursday, 5/25/2006 11:33:14 AM User: Linda Lacelle **Process Sheet** Drawing Name: LABEL PLATE Customer: CU-DAR001 Dart Helicopters Services Job Number: 27217 Part Number: D2506 Job Number: Seq. #: **Description: Machine Or Operation:** BRAKE NC 6.0 NC BRAKE Comment: NC BRAKE 1-Form as per dwg D2506 INSPECT WORK TO CURRENT STEP 7.0 Comment: INSPECT WORK TO CURRENT STEP PACKAGING 1 PACKAGING RESOURCE #1 8.0 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: wS・ 9.0 DC DOCUMENT CONTROL Comment: DOCUMENT CONTROL H06.01.21 Inspection Level 21 Job Completion



W/O:		WORK ORDER CHANGES												
DATE	STEP		Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector							
								:						
						-10		:						
				·										
						······································								

NCR:	*	WORK ORDER NON-CONFORMANCE (NCR)										
		Description of NC		Corrective Action Section B		Verification	Annescal	Ammercal				
DATE	STEP	Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date	Section C	Approval Design Mgr	Approval QC Inspector				
	:						1					
	,	я		+								
								÷				
							1					
						*						

Part No:	PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
NOTE: Date & initial all entries	S		QA: N/C Closed:	Date:

Qty:

Date:

Tuesday, 5/23/2006 11:36:11 AM

. User:

Kim Johnston

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

S.O. No. :

Job Number **Estimate Number** : 27217

: 10599

P.O. Number This Issue

: 5/23/2006

: NC

: 11 First Issue

: 26631

: PURCHASED PARTS Type

Part Number

Drawing Name

: D2506

Drawing Number

: D2506 REV D1

: LABEL PLATE

Project Number

: N/A : D1

Drawing Revision

Material

Due Date

: 6/15/2006

25 Um:

Each

Previous Run Written By

Prsht Rev.

Checked & Approved By

Comment

: Est.

01.06.08

Now laser cut EC

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

PURCHASING

PG 1.0



Issue P/O: Laser Cut per Dwg 2506

Material: AJ81 304/316 SS 20 gauge (0.040"

Material release note required

2.0

D2506F

Placard

1061051



Comment: Qty.:

1.0000 Each(s)/Unit

Total:

25.0000 Each(s)

Placard

3.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Recieive & Inspect for Transit Damage Ensure Material Release Note is attached

4.0

QC6

DIMENSIONAL CHECK



Comment: DIMENSIONAL CHECK

5.0

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

1-Deburr

W/O:		WORK ORDER CHANGES											
DATE	STEP	PROCEDURE CHANGE	В	У	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector					
	1					<u> </u>							

NCR:			WORK ORDER NON-CONFORMANCE (NCR)										
		Description of NC		Corrective Action Section B		Verification	Annroval	Approval					
DATE	STEP	Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date	Section C	Approval Design Mgr	Approval QC inspector					
				•			<u>.</u>						
							[
						4							
							1						
,						7	:						
<u> </u>							İ	<u> </u>					

Part No:	PAR #:	Fault Category:	NCR:	Yes	No	DQA:	Date:
NOTE: Date & initial all entries				QA: N	I/C C	osed:	Date:

Date: User:

Tuesday, 5/23/2006 11:36:11 AM

Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LABEL PLATE

Job Number: 27217

Part Number: D2506

Job Number:



Seq. #:

Machine Or Operation:

Description:

6.0

BRAKE NC

NC BRAKE



Comment: NC BRAKE

1-Form as per dwg D2506

7.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

8.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock Location:

9.0

DOCUMENT CONTROL



Comment: DOCUMENT CONTROL

DC

Inspection Level 21


Job Completion



W/O:			WORK ORDER CHANGES											
DATE	STEP PROCEDURE CHANGE						/ Date	Qty	Approval Mfg / Design Mgf	Approval QC Inspector				
		-1												
			A											
							٠							

NCR:		W	WORK ORDER NON-CONFORMANCE (NCR)											
		Description of NC		Corrective Action Section B		Verification	Approval	Approval QC Inspector						
DATE	STEP	Section A	Initial Design Mgr		gn & ate	Section C	Approval Design Mgr							
							,							
		G.					Ì							
			24				.							
							ļ 							
							<u> </u>							
		+												
						• •								
				,										

Part No:	PAR #:	Fault Category:	NCR:	Yes	No	DQA:	Date:
NOTE: Date & initial all entries				QA: N	I/C C	osed:	Date:



W/O:		WORK ORDER O					
DATE	STEP	PROCEDURE CHANGE	Ву	Date Qty	Approval Mfg / Design Mgr	Approval QC Inspector	
					į		
		*					

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
1		Description of NC		Corrective Action Section B	Verification		Approval				
DATE	STEP	Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date	Section C	Approval Design Mgr	Approval QC Inspector			
	·	·		·							
							i				
							1				
							1				
		-									
		4.									
-							1				

Part No:	PAR #:	Fault Category: N	ICR:	Yes No DQA :	Date:
NOTE: Date & initial all entries				QA: N/C Closed:	Date:

DART AEROSPACE LTD	Work Order:	27217
Description:	Part Number:	02506
Inspection Dwg: , Rev: V		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
	+/- 0.030	32.625	/		MOASUCIN	atape
39.00	+/-0.030	39.00	1		Measuring	FADE
4.50	+1-0.030	4.50	J		VerN	V
1.31	+1-0.030	1.31	√		VerN	
1.88	+1-0.030	1.86	V		vern	
			W-2-6-A			
					· · · · · · · · · · · · · · · · · · ·	
				T.		

			_		_	1
Measured by: M, M	Audited by:	(1	Prototype Approval:	2	A
Date: 06 06 12	Date:		06.06.13	Date:	V	/

Rev	Date	Change	Revised by	Approved
A		New Issue	KJ/JLM	

